



Correct Installation Orientation – 2014-1991 Honda & Acura Front Upper Ball Joint

Brand	Original Grade/Supreme	Product	Ball Joint	Date	June 2021
Part Number(s)	GK90469/MK90469				

To ensure proper part performance and prevent the possibility of premature failure, it is critical to press-in the below noted ball joint(s) in the correct orientation.

The identified part numbers are directional type ball joints; wherein they are designed to allow for an increased swing angle in a particular direction. Incorrect installation orientation of directional type ball joints may permit over travel of the ball stud in the improper direction, resulting in contact with the ball joint housing.

Part Number(s)

GK90469/MK90469

For a successful repair outcome, adhere to the following:

- Locate ball joint index mark. This may take the form of a hole, dimple, tab, notch or arrow. **See Figure 1.**
- Locate control arm index mark. This may take the form of a hole, dimple, tab, notch or arrow. **See Figure 2.**
- Do not contact ball joint backing plate during press-in.
- Ball joint index mark must align with control arm side index mark during installation. **See Figure 3.**



Figure 1. Ball joint index mark. In this example, the index mark is a hole.





Figure 2. Control arm index mark. In this example, the index mark is a hole.



Figure 3. Correct installation orientation is achieved when ball joint index mark aligns with control arm side index mark.

Always ensure to refer to the factory service manual for correct diagnostic procedures, component removal and installation methods and fastening torque values and procedures where applicable.