MEVOTECH INSIDER
Service Tips and Best Practices

2017-2011 GM Compact Sedan Front Lower Control Arm Compliance Bushing Bracket Bolt

Brand	Supreme	Product	Control Arm	Date	September 2022
Part Number(s)	CMS501133/CMS501134				

When ordering Mevotech Supreme replacement front lower control arms with the part numbers CMS501133 and CMS501134 for the vehicle applications listed below, it is important for the Professional Technician to note that the bushing bracket bolt is not pre-torqued out of the box.

This bushing bracket is provided loose, so the bracket can more easily be manipulated during installation of the control arm. This bolt will require final fastening with the proper torque value and suspension loaded to the correct ride height. **See Figure 1**.

Application(s)
2017-2012 Buick Verano
2015-2011 Chevrolet Cruze
2016 Chevrolet Cruze Limited
2015-2011 Chevrolet Volt



Figure 1. Bushing bracket bolt (circled above) must be correctly torqued after fitting control arm to vehicle

Always refer to the factory service manual for correct diagnostic procedures, component removal and installation methods, as well as fastening torque values and procedures where applicable. Only use a calibrated torque wrench for final fastening.

WE SUPPORT
ASE CERTIFICATION

DISCLAIMER: The information in this communication is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain vehicles. Refer to original manufacturers service manual for proper torque specifications and removal/installation procedures. All content in the publication is provided as-is and without warranty. All care has been taken to ensure the accuracy of the information presented. The publisher assumes no responsibility or liability for any loss or damage, direct, indirect or consequential, arising from the use of the information contained herein.