Labor Saver™: 2019-2011 GMC & Chevrolet 2500 HD/3500 HD Truck Front Lower Ball Joint

Brand	Supreme	Product	Ball Joint	Date	December 2022
Part Number(s)	MS50553				

The OEM (PN: 19256656 and various other OE-style) front lower ball joints for the applications listed below require to be staked/crimped after press-in.

Application(s):
2019-2011 Chevrolet Silverado 2500 HD
2019-2011 Chevrolet Silverado 3500 HD
2019-2011 GMC Sierra 2500 HD
2019-2011 GMC Sierra 3500 HD

Mevotech Supreme front lower ball joint MS50553 is engineered to utilize a circlip as the supplementary retention method. This reduces installation time for the Professional Technician and is a frustration-free alternative to the staking/crimping method. Additionally, the potential of damage to the control arm body is limited when securing the ball joint after press-in. **See Figure 1**.

MS50553 **OEM**




Figure 1. Mevotech Supreme front lower ball joint MS50553 can be secured to the control arm easily via the included circlip (left) vs OEM stake/crimp method (right)

WE SUPPORT ASE CERTIFICATION

DISCLAIMER: The information in this communication is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain vehicles. Refer to original manufacturers service manual for proper torque specifications and removal/installation procedures. All content in the publication is provided as-is and without warranty. All care has been taken to ensure the accuracy of the information presented. The publisher assumes no responsibility or liability for any loss or damage, direct, indirect or consequential, arising from the use of the information contained herein.