



Improved Design Factor Control Arms Ford Trucks • 4WD and 2WD







1	4WD	Ford F150, F250, Expedition	MK8722T MK8724T
1	2WD	Ford F150, F250, Expedition	MK8726T MK8728T
2	2WD 4WD	Ford F150, F250, Expedition	MK80014

 **Problem** as OE

- A** Non-greasable
- B** Twisting of control arm due to less material
- C** Ball joints cannot be replaced individually

 **Solution** MEVOTECH

- A** Greasable full-metal ball joint
- B** Reinforced neck for increased rigidity
- C** Replaceable ball joint




TORONTO
866-883-7075
MONTREAL
800-563-4280



www.mevotech.com | <http://partsonline.mevotech.com>

ME0150602

 (450) 978-9192 production@crdp.ca www.crdp.ca	Project # 4992	Client Mevotech	Description Ford Truck Control Arm flyer	Printing colours 4 process colours	Proof final 15/01/07 GD
	Artwork name 4992-Mevo_K8722T_eng.pdf	Final size 8.5" x 11"	Note		