



2017-2010 Chevrolet Equinox and GMC Terrain Front Lower Control Arm Compliance Bushing Bracket Nut

Brand	TTX/Supreme/Original Grade	Product	Control Arm	Date	November 2021
Part Number(s)	CTXMS50117/CTXMS50118/MS50117/MS50118/GS50117/GS50118				

When ordering Mevotech replacement front lower controls with the above-referenced part numbers for the vehicle applications listed below, it is important for the Professional Technician to note that the compliance bushing bracket nut is not pre-torqued out of the box.

This nut is provided loose, so the bushing bracket can be more easily manipulated during installation of the control arm (**see Figure 1**). It will require final fastening with the proper torque value and suspension loaded to the correct ride height.

Application(s)

- 2017-2010 Chevrolet Equinox
- 2017-2010 GMC Terrain




Figure 1. Bushing bracket nut (circled above) must be correctly torqued after fitting control arm to vehicle

Always refer to the factory service manual for correct diagnostic procedures, component removal and installation methods, as well as fastening torque values and procedures where applicable. Only use a calibrated torque wrench for final fastening.

