

Grease Fitting Location and Improved Ease of Access on Various Solid Axle Applications

Service Tips and Best Practices

MEVOTECH INSIDER

Brand	Original Grade/Supreme/TTX		Product	Ball Joint	Date	March 2021
Part Number(s)		GK8195T/MK8195T/TXMS50569				

As a result of differing clearance tolerances between the U-Joint yoke assembly and the bottom of the upper ball joint housing on some applications, Mevotech ball joints with the following part numbers (GK8195T/MK8195T/TXMS50569) feature a SAE compliant grease fitting which is located on the side of the ball joint housing.

The grease fitting has been located to the side of the ball joint housing to prevent possible interference with the yoke assembly as it rotates. Furthermore, this location improves both ease of installation and ease of access for the Professional Technician during a future lubrication service.

Technical Support Hotline: 1.844.572.1304

For parts go to: mevotech.com

Publication Number: MI-21-057-01-01-E



WE SUPPORT ASE CERTIFICATION

DISCLAIMER: The information in this communication is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain vehicles. Refer to original manufacturers service manual for proper torque specifications and removal/installation procedures. All content in the publication is provided as-is and without warranty. All care has been taken to ensure the accuracy of the information presented. The publisher assumes no responsibility or liability for any loss or damage, direct, indirect or consequential, arising from the use of the information contained herein.