MEVOTECH INSIDER
Service Tips and Best Practices

2006-1990 Jeep Front Lower Ball Joint: Correct Installation Orientation


Brand	TTX	Product	Ball Joint	Date	August 2021
Part Number(s)	TXK3161T				

For the applications below, the ball joint housing must be oriented correctly during press in to ensure adequate access to the grease fitting for relubrication service.

Application(s)

2001-1990 Jeep Cherokee
1992-1990 Jeep Comanche
1998-1993 Jeep Grand Cherokee
1993 Jeep Grand Wagoneer
2006-1997 Jeep TJ
1990 Jeep Wagoneer
1995-1990 Jeep Wrangler
2006-1997 Jeep Wrangler

The ball joint must be installed with the grease fitting positioned parallel to the lower knuckle stop out tab. This will ensure sufficient clearance for any relubrication service. **See Figure 1.**



Always refer to the original factory service manual for proper diagnostic, removal and replacement procedures, as well as for all related torque specifications and values. Only use a calibrated torque wrench for final fastening.

WE SUPPORT
ASE CERTIFICATION

DISCLAIMER: The information in this communication is intended for use only by skilled technicians who have the proper tools, equipment and training to correctly and safely maintain vehicles. Refer to original manufacturers service manual for proper torque specifications and removal/installation procedures. All content in the publication is provided as-is and without warranty. All care has been taken to ensure the accuracy of the information presented. The publisher assumes no responsibility or liability for any loss or damage, direct, indirect or consequential, arising from the use of the information contained herein.