



Labor Saver™: 2009-2005 Nissan 350Z and 2007-2005 Infiniti G35 Front Lower Forward Control Arm Tapered Sleeve

Brand	Supreme	Product	Control Arm	Date	November 2022
Part Number(s)	CMS301030/CMS301031				

During a front lower forward control arm replacement service on certain Nissan and Infiniti RWD coupes, in some cases the ball joint tapered sleeve will become seized to either the ball joint or into the old control arm bore.

If the sleeve must be removed either for re-use, it must be separated carefully. A combination of penetrating oil and a three-jaw puller will usually suffice. All rust and corrosion must be cleaned from the sleeve. Additionally, the sleeve and mating component must be inspected for any damage and or an 'out-of-round' condition. Do not re-use the sleeve or mating component if signs of damage or abnormal wear are found during inspection.

However, if the sleeve cannot be reused or is damaged a new one must be sourced.

The below noted Mevotech Supreme front lower forward control arms include a new anti-corrosion coated sleeve for a frustration-free installation. **See Figure 1.**

Part Numbers:

- CMS301030 – Front Left Lower Forward
- CMS301031 – Front Right Lower Forward



Figure 1. Mevotech Supreme front lower forward control arms for the 2009-2005 Nissan 350Z and 2007-2005 Infiniti G35 RWD feature a new tapered sleeve and ball joint to control arm nut as part of the hardware package, saving time and providing more value in a repair option for the Professional Technician

